



x1



x2



x4/x5/x6



x2



x2



x1



St4x40

Ø6x30

x2




St5x40

x6



M4


x4




1

$$\begin{matrix} H_0 \\ L_0 \end{matrix} \Rightarrow d \text{ \& } H_1$$


a)




L_{Track} [mm]	1950	2400	3000
X [mm]	840	1120	1400
n [szt]	4	5	6




b)



H_1





216-110
216-111






$H_1 = H_0 + 81$
 $H_1 = h + 61$







2




3




4





5




x2



#5








6



2xSt4x40




2xØ6x30





7

x2



#2



321-090
321-091



x2



7a



7b

