


x1



x2



x5




x2




x2



x1



x4




x4



x5



x5




x2




x2




1




a)




b)







St 8x90
(x5)




Ø10x30 (x5)




M8x60 (x5)






2



1



2° $d \geq 930\text{mm}$



3

1 M10x55 s=35→40

2 M10x60 s=40→45

s

1

2

4x $\varnothing 6$

4x $\varnothing 10$


40

90


A=75



216-088



A [mm]=130



4

5

$\varnothing 6$

2











3

1



C/04/2021

6



7

